

6233072

1/7




FIG. 1




FIG. 2

3/7


Operation of the
Optical Cross Connect

FIG. 3




FIG. 4A




FIG. 4B

6/7

Second Failure - Module 3




FIG. 4C

7/7




FIG. 5